

CLASSIFIED MESSAGE

ORIG :
 UNIT :
 EXT :
 DATE : 24 NOV 70

S E C R E T

ROUTING

1		4	
2		5	
3		6	

25 Nov 70 11 45

TO :
 FROM :
 CONF :
 INFO :

	DEFERRED	PRIORITY	INITIALS
X	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

001 71266

PAGE 1 OF

TO

IDEALIST

INFO

CITE

9867-

REF: 6038 (IN 63242, 28 OCT 70)

1. AS PER REF, FILM FROM SEVERAL OLD HEAD MSNS WAS ANALYZED FOR PROCESSING DEFECTS, CURRENTLY IDENTIFIED AS "WATER SPOTS". MORE SPECIFICALLY, FILM FROM MSNS G-122 - 3 JUN 70, G-134A - 19 SEP 70, G-139 - 6 OCT 70, AND G-143A - 16 OCT WAS EXAMINED.

2. THE APPARENT WATER/MOISTURE SPOTS (GLOBULAR-SHAPED), AS DESCRIBED IN THE EVALUATION OF G-143A WERE NOT DETECTED ON ANY OTHER FILM EXAMINED. THEY WERE ONLY DETECTED IN FRS 1 - 308 OF G-143A AND TERMINATE AT THE HEAT SPLICE IN FR 308. THIS CORRELATES TO JUST ONE PROCESSING PART OF MSN G-143.

END OF MESSAGE

COORDINATING OFFICERS

S E C R E T

CHIEF, TSG/NPIC
 RELEASING OFFICER

CHIEF, APSD/TSG/NPIC
 AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.
 Signal Center Transmission Copy - DO NOT DETACH - Forward with Master